

VEHICLE INSPECTION REPORT

LX17CTU

Mercedes-Benz Sprinter 514 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 16/03/2017

Fuel Type DIESEL

Body Style Minibus

Year 2017

Colour WHITE

MOT Due 15/03/2027

Mileage 190,466 Km Warranted

VIN WDB9066552P329687

Gearbox AUTOMATIC

14 SEATS + DRIVER, WHEELCHAIR LIFT, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Park assist camera
- Rear parking sensor
- Front electric windows

Photos






Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: B Post ns
Rusted
Over 5mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



9: Door osf
Dented
With Paint Damage

10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		OK	
OK		No	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK